1681

OPERABLE UNIT 4

9-24-90

DOE/ASI DOE-1772-90 1 LETTER



FMPC Site Office
P.O. Box 398705
Cincinnati, Ohio 45239-8705
-513) 738-6319

1681

SEP 2 4 1990

DOE-1772-90

John D. Wood, Project Director Advanced Sciences, Inc. 11003 Hamilton-Cleves Road P. O. Box 475 Ross, OH 45061

Dear Mr. Wood:

OPERABLE UNIT 4

During discussions with U.S. EPA and Ohio EPA it became apparent that changes need to be made to continue the Feasibility Study Process for Operable Unit 4. Significant changes include dividing OU4 into Sub-Operable Units (SOUs), and incorporation of the proposed K-65 Removal Action into the evaluation of alternatives.

The following divisions are recommended:

Sub-Operable Unit 4A - K-65 residues

Sub-Operable Unit 4B - K-65 Silo (Silos 1 & 2) structures, berms, and contaminated soils

Sub-Operable Unit 4C - Metal Oxide Silo 3

Sub-Operable Unit 4D - Metal Oxide Silo 4 (empty)

ASI/IT is directed to make the necessary changes in OU4 as outlined above to continue FS work. Work should continue on the FS Report for Sub-Operable Units 4A, 4B, 4C, and 4D, assuming 40 CFR 191 is not an ARAR. The FS Report and the OU4 schedule could be revised at a later date if 40 CFR 191 becomes an ARAR.

If you have any questions, please contact Jack Craig, at (513) 738-6159.

Sincerely,

Bobby Davis

Contracting Officer's

Representative

DP-84:Craig